



#### OBSERVATIONS:

- PRIMARY PEDESTRIAN CROSSING AREAS ARE ENHANCED OR MARKED
- SIDEWALK SYSTEM IS EXTENSIVE; GAPS SHOULD BE FILLED

