


SAMPLES OF EXISTING CONDITIONS



OBSERVATIONS:

-USES SOUTH OF CHURCH STREET VARY WIDELY WITH SIGNIFICANT AMOUNTS OF SURFACE PARKING    -MEDICAL USES DOMINATE EAST END OF MAIN STREET CORRIDOR

